

UTAH STATE CAPITOL ARCHITECTURE: EXTERIOR SURVEY REPORT

ELEVATION LOCATION: NORTH ELEVATION

Survey Date: 4/25/00

Code: EX-001

Description: Foundation stone

Location: East side

Grid: B

Condition: J, PAT

Mortar joint damage and poor quality patching

Comments: B/E 113



Code: EX-001

Description: Foundation stone

Location: center

Grid: E21-B, W 21

Condition: J

Mortar joint with missing or loose mortar

Comments: where concrete meets stone



Code: EX-001

Description: Foundation stone

Location: West side

Grid:

Condition: J

Mortar joint with missing or loose mortar

Comments: W 49-B, W 155-B, W 170-B



Code: EX-001

Description: Foundation stone

Location:

Grid:

Condition: ST, C, B

Comments: ST--W 100-B



Code: EX-001

Description: Foundation stone

Location: West entrance

Grid: W 198-B

Condition: INT

Intrusive, non-original, non-essential element

Comments: metal pipe



Code: EX-001

Description: Foundation stone

Location: North Elevation West side

Grid: B/ W-155

Condition:

Comments: J



Code: EX-001

Description: Foundation stone

Location: North elevation West side

Grid: B/ W-170

Condition:

Comments: J



Code: EX-001

Description: Foundation stone


Location: North elevation West side

Grid: B/ W -150

Condition: ST

Significant Staining; may indicate rusted connector

Comments: ST



Code: EX-001

Description: Foundation stone

Location: North elevation west side

Grid: B / W -130

Condition:



Comments: C

Code: EX-001

Description: Foundation stone


Location: North Elevation west side

Grid: B/W-100

Condition: BR

Broken, severely cracked or
chipped

Comments: B



Code: EX-006

Description: Pilaster shaft

Location: North Elevation East entrance

Grid: D & C/ E150

Condition:



Comments: PAT

Code: EX-006

Description: Pilaster shaft

Location: North Elevation east side

Grid: E/135

Condition:



Comments: PAT



Code: EX-006

Description: Pilaster shaft

Location: North Elevation East side

Grid: E / E 71

Condition:



Comments: PAT

Code: EX-006


Description: Pilaster shaft

Location: North elevation West side

Grid: E/ W- 190

Condition: PAT

Poor quality, non-matching patch



Comments: Pat

Code: EX-008

Description: Wall stone

Location: North Elevation East side

Grid: D & E/ E 127

Condition:



Comments: PAT


Code: EX-008

Description: Wall stone

Location: North elevation East side

Grid: E/ E 115

Condition:



Comments: PAT




Code: EX-008

Description: Wall stone

Location: North Elevation East side

Grid: E / E75

Condition:



Comments: PAT

Code: EX-008

Description: Wall stone

Location: North Elevation West side

Grid: E/ W -105

Condition: PAT

Poor quality, non-matching patch



Comments: PAT

Code: EX-009

Description: Entablature lower belt

Location:

Grid: W 99-F, W 115

Condition: PAT

Poor quality, non-matching patch



Comments:

Code: EX-034

Description: Column shaft

Location: North elevation East side

Grid: E-E 182

Condition:



Comments: Bad patch



Code: EX-094

Description: Trim

Location: East entrance

Grid: E typical

Condition: PAT

Poor quality, non-matching patch



Comments: D&E/ E190

Code: EX-094


Description: Trim

Location: North Elevation West side

Grid: E/ W-155

Condition: PAT

Poor quality, non-matching patch



Comments: PAT

